

# 水準点現況調査写真

調査年月日 平成 21 年 11 月 日

標 識 番 号	0 0 1 - 0 2 9
所 在 地	横浜市神奈川区西神奈川 1 丁目 9-1 地先
 A close-up photograph showing a silver leveling staff mounted on a tripod on the left. To its right is a red and white striped leveling staff. Further right is a benchmark marker, which is a white cylindrical cap with a blue triangle and the number '29.5' written on it. The scene is outdoors with some greenery and a concrete curb.	
 A wide-angle photograph showing the benchmark location on a sidewalk. A green utility box is visible on the left. A red and white striped leveling staff is positioned near the benchmark. In the background, there is a street with a traffic light, a crosswalk, and buildings, including a green building with arched windows.	
備 考	: 小児療育センター前 国道 1 号 歩道