

# 水準点現況調査写真

調査年月日 平成 21 年 11 月 日

標 識 番 号	1 0 9
所 在 地	横浜市神奈川区入江一丁目 13-16
 A close-up photograph of a leveling point marker. It consists of a black tripod-like base with three legs, mounted on a concrete block. A red and white leveling staff is attached to the top of the marker. The marker is situated in a grassy area with several large, dark grey stones around it. A concrete wall is visible on the right side of the frame.	
 A wide-angle photograph showing the leveling point marker in its surroundings. The marker is located in a grassy area between a large tree on the left and a blue building on the right. In the background, there is a fence and a bicycle. The marker is a small black tripod on a concrete block, with a red and white leveling staff attached to it.	
備 考	: 一の宮神社