

水準点現況調査写真

調査年月日 平成 21 年 11 月 日

標 識 番 号	9 2 5
所 在 地	横浜市港北区烏山町 814
 A close-up photograph showing a leveling staff with a white top and a red and white striped middle section, positioned vertically in a hole dug into the ground. The soil is dark and appears moist. The hole is lined with dark material, possibly a tarp or plastic.	
 A photograph showing a leveling staff with a white top and a red and white striped middle section, positioned vertically in an outdoor setting. The staff is mounted on a concrete base. In the background, there is a green chain-link fence and some green plants. To the left, there are several dark, curved objects, possibly pipes or conduits, leaning against the fence.	
備 考	: 城郷小学校